

**List of H2S caution signs - medium
and high risk - Kralupy refinery**



<i>item</i>	<i>operation</i>	<i>number</i>	<i>risk</i>
1.	STRUCTURE no. 2516	31	HIGH
2.	STRUCTURE no. 2517		
3.	STRUCTURE no. 2513	20	HIGH
4.	STRUCTURE no. 2514		
5.	STRUCTURE no. 2512	19	MEDIUM
6.	STRUCTURE no. 2625	2	MEDIUM
7.	STRUCTURE no. 2414	15	HIGH
8.	STRUCTURE no. 2417		
9.	STRUCTURE no. 2413	3	HIGH
10.	STRUCTURE no. 2451	9	MEDIUM